

Cisco Switchingハブ設置状況

調査日:2012/03/30

スイッチ名	設置場所	ping	現場確認	備考
c2960s-01	mon6A	○	○	
c2960s-02	KL_61横 試験部屋	○	○	
c2960s-03	monRA	○	○	
c2960s-04	加速管組立ホール	○	○	
c2950-5	vxi-c-2	○	○	ラベル無し
c2950-6	monAA	○	○	
c2950-7	monAB	○	○	
c2950-8	monBA	○	○	
c2950-9	monBB	○	○	
c2950-10	monCA	○	○	
c2950-11	monCB	○	○	
c2960s-12	第1副制御室	○	○	
c2960s-13	vxi-a-2	○	○	
c2960s-14	vxi-b-2	○	○	
c2960s-15	vxi-b-6	○	○	
c2960s-16	vxi-c-6	○	○	
c2960s-17	vxi-1-2	○	○	
c2960s-18	vxi-1-6	○	○	
c2960s-19	vxi-2-1	○	○	
c2960s-20	vxi-2-6	○	○	
c2960s-21	vxi-3-2	○	○	
c2960s-22	vxi-3-6	○	○	
c2960s-23	vxi-4-2	○	○	
c2960s-24	vxi-4-6	○	○	
c2960s-25	vxi-5-2	○	○	
c2960s-26	vxi-5-6	○	○	
c2960s-27	第2副制御室	○	○	
c2960s-28	第3副制御室	○	○	
c2960s-29	第4副制御室	○	○	
c2960s-30	第5副制御室	○	○	
c2960s-31	ABC副制御室	○	○	
c2960s-32		×		未購入(予備品)
c2960s-33		×		未購入(予備品)
c2960s-34	mon1A	○	○	
c2960s-35	mon1B	○	○	
c2960s-36	mon3A	○	○	
c2960s-37	mon3B	○	○	
c2960s-38	mon4A	○	○	
c2960s-39	mon4B	○	○	
c2960s-40	mon5A	○	○	
c2960s-41	mon5B	○	○	
c2960s-42	mon2A	○	○	
c2960s-43	mon2B	○	○	
c2960s-44	A1電子銃室	○	○	
c2960s-45	slow e+ モニタラック	○	○	